


Voltmeter conversion



1 of 6


Step 1 · Disconnect the battery



Take the **negative (-) cable** off the battery. Move the cable away from the post. Leave it off until the job is done.


TIP: Keep the battery cable off while you drill and wire.

Step 2 · Remove the cluster



Take the cluster out of the dash. Unplug the wire plugs. Unhook the speedometer cable. Mark the plugs so they go back in the same place.

Step 3 · Take the board apart



Take the motherboard off the back of the cluster. Take off the gauges, bulb holders, screws, and loose parts.


Leave a **bare board** and **two separate metal plates**. Keep the oil gauge and all the hardware. Set the old ammeter aside.

Drill the motherboard



2 of 6


Step 4 · Mark the two new holes



Use the card marked **“Printed mother board template.”** Line up its two holes with the old ammeter holes.


Put the center punch on each red dot. **Tap lightly.** Keep the two marks lined up.

Step 4 · Check the marks, then drill




Take the card off. Check that both marks are **above the copper ribbon**. Do not cut the ribbon.

Start with a **3/32-inch pilot hole**, or a bit close to that size. Drill each mark in the order below. Keep each larger bit clear of the ribbon.



TIP: The holes may look a little left of center. That is correct. Do not move them.




TIP: On old boards, the thin bridge between each old and new hole may break. The gauge still works if the copper ribbon stays whole.

Drill the metal plate



3 of 6

Step 5 · Use the metal template



Set the plate on a scrap 2×4. Use the **“Metal Backing Plate Template.”** Put the metal prongs through the card’s holes.

LEFT HOLE: Grind or sand off the small tab below the left round hole. A Dremel works well. Take the card off.

Start with **5/32 inch** (or oval the hole with a bevel grinding tool). Then drill **7/32 inch**.


TIP: After 5/32 and 7/32, flip the plate. Put the L-bracket DOWN on the 2×4.

TIP: Clamp the plate to a scrap 2×4. This holds it still and saves your counter top.


Then drill **9/32 inch**, followed by **11/32 inch**.

RIGHT HOLE: Set the card back in place. Lightly punch the red dot. Take the card off.

Drill **3/32**, then **7/32**, then **9/32**, then **11/32 inch**. The old and new holes will join.



Step 6 · Make the plate smooth



Sand the edges on **both sides** until smooth. Brush off all chips.

If the plate bent, use a small hammer and a metal backer to make it flat.



TIP: Paint if you like. Keep screw and ground contact spots bare.

Open the SunPro gauge



4 of 6


Step 7 · Open the box



Open the SunPro box. Set its paper instructions aside. **Save the hardware bag.** Before you open the metal case, mark which gauge post is + and which is -.


WARNING: Do not hit, smack, or shake this gauge.

Step 8 · Pry up the front rim




Lay the gauge face down on a soft cloth on a flat surface. Work around the outside rim. Pry the black metal faceplate away from the case a little at a time.

WARNING: Keep BOTH nuts on until the black faceplate is off. The nuts hold the gauge in place.



Use small side cutters to make small relief cuts around the outer lip. Keep the tool away from the needle, face, and coil.

Step 9 · Lift the gauge out



Once the black faceplate is off, take off the two nuts. Lift the gauge out of the case. Keep the nuts and washers.

TIP: Save the red isolator. You will use it again.


Fit the gauge and join wires



5 of 6


Step 10 · Put the board back together

Put the metal plates, oil gauge, and other parts back on the board. Fit the voltmeter where the ammeter was. Reuse the **red isolator** on the back, as shown. Use the saved hardware. Fit the **OIL / VOLT** label before closing the cluster.



SAVED RED ISOLATOR

BACK OF CLUSTER




WARNING: Plastic must go ALL THE WAY through the metal plate. Only plastic may touch the edge of the hole.


A metal post, ring, washer, or nut touching the plate will cause a short and can blow a fuse. Enlarge and smooth the hole if needed.

Step 11 · Join the old red and yellow wires

BEST: SOLDER + HEAT SHRINK



OR: CRIMP BUTT CONNECTOR



**JOIN TO EACH OTHER
KEEP BOTH OFF THE VOLTMETER**

Best: Slide heat shrink on first. Solder the two heavy wires together. Slide the tube over the joint, then heat it tight.

Or: Use the butt connector if it fits both heavy wires. Crimp with a crimp tool. Tug both wires. Leave no bare metal.

Wire the meter and test




6 of 6


Step 12 · Use the two blue T-taps

Tap the Jeep's **red ignition wire** at the round plug (**pin 11**). Tap the **black ground wire** at the wide plug (**pin 4**). The red ignition wire has 12 volts with the key ON.



CLUSTER PINS — VIEWED FROM THE BACK



BLACK GROUND · PIN 4
WIDE PLUG




RED IGNITION · PIN 11
ROUND PLUG



Put each wire in a tap. **Do not cut the Jeep wire.** Squeeze the tap shut with pliers. Push the kit's spade plug in all the way.

TIP: The Blue Taps Fit 18-14 AWG wire.



Kit RED → gauge +
Kit BLACK → gauge -
Put each kit ring on its marked post. Fit the hardware snugly.

Step 13 · Put the cluster back and test



Plug in the wire plugs and speedometer cable. Fasten the cluster.

Reconnect the negative battery cable.

Key ON, engine off: about 12 volts.

Engine running: usually 13-15 volts.

WARNING: If a fuse blows or a wire gets hot, unhook the battery. Do not use a larger fuse.